












































Catalogo Suzuki

Marca	Modelo	Aire	Aceite	Combustible	Habitaculo
Suzuki	BALENO - 1.0 L INY. NAFTA 8v (2003 >)	SB-S926 	VX-114 	FI-8360 	AKX-3536 
Suzuki	BALENO - 1.6 L INY. NAFTA 16v (> 1997)	SB-S936 	VX-103 	FI-8730 	
Suzuki	BALENO - 1.6 L INY. NAFTA 16v (1998 >)	SB-S936 	VX-103 	FI-8730 	
Suzuki	FUN - 1.4 L INY. NAFTA 8v (2004 >)	SB-S926 	VX-114 	FI-8360 	AH-0179 
Suzuki	FUN - 1.4 L INY. NAFTA 8v 90 CV (2006 >)	SB-S926 	VX-114 	FI-8360 	AH-0179 
Suzuki	FUN - 1.6 L INY. NAFTA 16v (1998 >)	SB-S934 	VX-104 	FI-8300 	AH-0145 
Suzuki	FUN - 2.0 L INY. NAFTA 16v (1998 >)	SB-SE00 	VX-104 	FI-8660 	AH-0145 
Suzuki	FUN - 2.5 L INY. NAFTA V6 (1998 >)	SB-SE00 	VX-104 	FI-8660 	
Suzuki	G. VITARA - 2.0 L MOT. MAZDA (2002 >)	SB-SE00 	VX-112 	AC-1001 	AH-0145 
Suzuki	G. VITARA - 2.0L HDI (PEUGEOT) (2003-2005)	SB-SE00 	VX-105 	EF-14010 	AH-0145 
Suzuki	G. VITARA - 2.7 L (XL7) V6 (2006 >)	SB-S937 	VX-104 		
Suzuki	G. VITARA - J-III 2.0 D 16v 140 CV (2007 >)	SB-SJ03 	VX-104 	FCD-0767 	AH-0146 
Suzuki	G. VITARA - J-III 2.4i 16v 165 CV (2010 >)	SB-SJ04 	VX-104 		AH-0146 
Suzuki	JIMNY - 1.3 L INY. NAFTA (1998-2002)	SB-S939 	VX-104 	FI-8430 	AKX-1974 
Suzuki	JIMNY - ALTO 800 cc ()	SB-S925 	VX-102 		
Suzuki	MARUTTI - 0.8/1.0 L INY. NAFTA (1996-2000)	SB-S925 	VX-104 	FI-8650 	
Suzuki	MARUTTI - 800 cc CARBURADOR ()	SB-S925 	VX-102 	CF-1045 	
Suzuki	SAMURAI - 1.0 L INY. NAFTA 3P/5P (> 1996)	SB-S917 	VX-104 	FI-8230 	
Suzuki	SAMURAI - 1.3 L CARBURADOR 3P/4P (> 1997)	SB-S917 	VX-104 	CF-1035 	
Suzuki	SAMURAI - 1.3 L GTI (> 1997)	SB-S163 	VX-104 	FI-8230 	
Suzuki	SAMURAI - 1.3 L INY. NAFTA (> 1999)	SB-S915 	VX-102 	FI-8430 	
Suzuki	SWIFT - 1.5 16v (HUNGRIA) (2007 >)	SB-SJ00 	VX-104 		AKX-1972 
Suzuki	SWIFT - 1.6 CARBURADOR (> 1995)	SB-S932 	VX-104 	CF-1035 	AH-0148 
Suzuki	SWIFT - 1.6 INY. NAFTA 16v (> 1995)	SB-S924 	VX-104 	FI-8230 	

Suzuki	SX4 - 1.6 L CARBURADOR (> 1991)	SB-S923 	VX-102 	CF-1025 	
Suzuki	SX4 - 2.0 L 16v 135 CV (2010 >)	SB-S410 	VX-104 	ESF-21010 	CA-14040 
Suzuki	VITARA - 1.6 L CARBURADOR (1992-1998)	SB-S922 	VX-102 	CF-1025 	
Suzuki	VITARA - 1.6 L INY. NAFTA (> 1995)	SB-S934 	VX-102 	FI-8300 	
Suzuki	VITARA - 2.0 TDI (1997-1998)	SB-S923 	VX-104 	AC-1001 	

Copyright Filtros Faro Todos los derechos reservados